


Attorney Docket No. 381NP/50933 Filed: February 27, 2002 Sheet 1 of 8



Attorney Docket No. . 381NP/50933 Filed: February 27, 2002 Sheet 2 of 8





Attorney Docket No. . 381NP/50933 Filed: February 27, 2002 Sheet 3 of 8





FIG. 5



Attorney Docket No. . 381NP/50933 Filed: February 27, 2002 Sheet 4 of 8




FIG. 6(b)






FIG. 6(c)

SERVICE INTERRUPTION OR AC-DC CONVERTER FAULT





Attorney Docket No. . 381NP/50933 Filed: February 27, 2002 Sheet 5 of 8

FIG. 7




Attorney Docket No. . 381NP/50933 Filed: February 27, 2002 Sheet 6 of 8





Attorney Docket No. . 381NP/50933 Filed: February 27, 2002 Sheet 7 of 8

FIG. 9



Attorney Docket No. . 381NP/50933 Filed: February 27, 2002 Sheet 8 of 8

FIG. 11(a)

OPERATION PATTERN OF CONVENTIONAL EQUIPMENT BUILT-IN BACKUP POWER SOURCE

STATIONARY STATE




FIG. 11(b)

DURING SERVICE INTERRUPTION

